REFERENCE LIST



2022 Milan, Italy **Textile**

A tannery is a very aggressive working environment for machinery. After 11 years of work, a pair of exchangers needed maintenance to restore them to their original condition.

We have therefore realised a thermal and energy efficiency of the machines. This is in line with the policy of high leather goods brands that demand a supply chain compatible with their carbon footprint.

